



3 units of Komatsu HD785 Main Body

Discharge from vessel and local transport in Walvisbay for storage at transporter's premises, until arrangements of Permits and escorts for final transport to final destination Kinsevere mine, Lubumbashi, RDC





3 units of Komatsu HD785 Body

Discharge from vessel and local transport in Walvisbay for storage at transporter's premises, until arrangements of Permits and escorts for final transport to final destination Kinsevere mine, Lubumbashi, RDC



3 units of Komatsu HD785 Main Body

On their way.. over Zambia.

Passing weighbridges, cable-lifting required, and struggling with some parts of difficult road. This while police and escorts make necessary arrangements for safe traffic passage...



3 units of Komatsu HD785 Body

Crossing Lubumbashi, after import customs clearance



3 units of Komatsu HD785 Body

And finally arrived at the Kinsevere Mine, after a long trip with a lot of obstacles and difficulties...